

Somerton Town Council 8 Cary Court, Somerton Business Park, Somerton, TA11 6SB

Tel/Fax: 01458 272236

town.clerk@somertontowncouncil.gov.uk

SPECIFICATION MAIN ENTRANCE ROADS AND OTHERS SOMERTON

SOMERTON			
SECTION A			
VERGE TO BE CUT	DISTANCE	WIDTH OF CUT	STRIMMING IF NEEDED
B3153 going out of Somerton Langport Road and Somerton Hill from Gassons Lane on right including sight line.	Approx. 1,275 metres.	Complete width of verge avoiding bulbs in Spring at entrance to Sportsfield and around trees.	Carefully around trees not in Spring as bulbs planted. Edge of ditch if needed.
Cartgate Lane on left. Both corners at junction of B3153 with B3151 and Horsemill Lane. B3153 both sides. Verge on N Side of B3151 Lodge Hill.	Approx. 635 metres. Approx. 55 metres. Level with track on left.	Avoid flower hot spots. Complete width of verge avoiding bulbs in Spring on left hand side.	Avoid flower hot spots. If needed beware of bulbs.
B3165 Sutton Road seating area end of Ricksey lane both sides to Somerton sign.	Approx. 110 metres.	From kerb to tree line taking care to avoid bulbs in Spring.	If needed beware of bulbs.
Cedar Grove seating area at end of Cemetery Lane.	Approx. 27 metres.	Corner area back to wall.	If needed.
Etsome Road to Beech Grove seating area.	Approx. 160 metres.	From kerb to fence and area around seat. (kerb-fence-kerb).	If needed.
Cemetery Lane	Approx. 225 metres.	Central width 4 metres. Leaving wild flowers at sides.	Under instruction from Accessibility and Highways committee.
Sight Line			
Along north side of Langport Road just before Bancombe Road Junction with B3153			

To work in consultation with the Chair/Vice Chair of Accessibility and Highways Committee.

Price section A of 12 cuts a season from April 2015 to October 2015 and April 2016 to October 2016 and for 4 Cuts on Section B. (Fixed Term 2 year Contract).

Please also provide a cost/cut for any additional cuts required during the period of the contract. Height of grass to be cut to 5cms.

Map of routes included, a map of flower hot spots will be provided later.

Operatives must have all relevant qualifications and Public Liability Insurance.